

FROGMAN ENTERPRISES

PO Box 2363, Pleasant Hill, CA 94523 USA (925) 586-6420
 <Steve@BevelHeaven.com> <http://www.FEzone.com> <http://www.BevelHeaven.com>



Thank you for purchasing the BevelHeaven Electric Start Bevel Drive stainless steel fastener kit! I suggest you clean everything up on your motor then remove one bolt at a time, replacing it with the appropriate fastener. I suggest that you put some anti sieze on the bolt and torque it per manufacturer spec. That is it, just check off the fasteners as you work your way down the list!

Description	Quantity	Size & Description
Clutch Cover	10	M6 x 30 Cap Screw
Starter Cover	5	M6 x 25 Cap Screw
Clutch Inspection Cover	2	M6 x 14 Flat Head Allen or Slotted
Cam Block Cover	8	M6 x 25 Cap Screw
Valve/Rocker Cover	16	M6 x 20 Cap Screw
Bevel Cover	6	M6 x 20 Cap Screw
Lower Bevel Tower	8	M6 x 20 Cap Screw
Alternater Cover	8	M6 x 25 Cap Screw
	1	M6 x 50 Cap Screw
	1	M6 x55 Cap Screw
Breather Cap	1	M6 Locknut
Intake Manifold	4	M8 Locknut
	4	M8 Washer
	2	M5 x 8 Button
	2	M5 Alloy Crush Washer
Sprocket Cover	3	M6 x 20 Cap Screw
	1	M8 x 25 Cap Screw
Case Halves	8	M6 x 30 Cap Screw
Starter Motor	2	M4 x 8 Cap Screw
	2	M4 Washer
	2	M6 x 150 Cap Screw
	2	M6 lockwasher
Oil Filter Cover	1	M10 x 15 Button
	1	M10 Alloy Crush Washer
Kick Starter Bolt	1	M8 x 30 Cap Screw